

# Material Safety Data Sheet

Slickcoat-B

Trade Name As Used On Label

Foundation Technologies, Inc.  
PO Box 491718  
Lawrenceville, GA 30049 USA  
800-773-2368/678-407-4640/Fax 678-407-4645

PREPARED BY: J. R. SMITH  
AUGUST 2010  
24 HR. EMERGENCY# 800-424-9300  
(INTL. EMERGENCY# 703-527-3887)

## I. PHYSICAL DATA

Boiling Point: >150°F.  
Specific Gravity (H<sub>2</sub>O=1): >1.0  
Vapor Pressure (mm Hg and Temperature): < 1.3mm Hg @ 20°C  
Melting Point: N/A  
Vapor Density (Air=1): Lighter than air  
Evaporation Rate (Butyl Acetate=1): Slower than Butyl Acetate  
Solubility in Water: Soluble

## II. MATERIAL IDENTIFICATION AND INFORMATION

COMPONENTS - Chemical Name & Common Names (Hazardous Components 1% or greater; Carcinogens 0.1% or greater)	%	OSHA PEL	ACGIH TLV	OTHER LIMITS RECOMMENDED
Polyamine Solution Cas# 68410-23-1	47	...	...	.....
2-Propoxyethanol Cas# 2807-30-9	26	...	...	.....
Methyl Alcohol Cas# 67-56-1	2	200ppm Skin STEL	250ppm Skin STEL	.....
Proprietary Resin/Pigment Mixture Cas# 577-11-7 ... Not Established	8			
<b>Non-Hazardous Ingredients</b>	<b>17</b>			
<b>TOTAL</b>	<b>100</b>			

## III. FIRE AND EXPLOSION HAZARD DATA

Flash Point and Method Used: 150° F Seta Flash  
Auto-Ignition Temperature: N/A  
Flammability Limits in Air, % by Volume: N/A  
LEL: N/A  
UEL: N/A  
Extinguisher: Dry foam, Carbon Dioxide; use aqueous foam or water for large fires  
Special Fire Fighting Procedures: Remove all ignition sources. Wear self-contained breathing apparatus and complete personal protective equipment.  
Unusual Fire and Explosion Hazards: None

#### IV. HEALTH HAZARD DATA

Primary Routes of Entry: Inhalation, Ingestion, Skin Absorption

Effects of Overexposure: Possible skin rash. May damage eyes. Contains solvents that have the potential to cause headaches, nausea, dizziness and respiratory irritation.

Emergency and First Aid Procedures: Wash hands and eyes with plenty of soap and water. If ingested drink plenty of water. In case of exposure to a high concentration of vapor or mist remove person to fresh air. If breathing has stopped administer artificial respiration and seek medical attention. Call Physician.

#### V. REACTIVITY HAZARD DATA

Stability: \_\_\_ UNSTABLE \_\_\_X\_\_\_ STABLE

Conditions to Avoid: Open flame, spark, and high heat.

Incompatibility (Materials to Avoid): Strong acids, bases, amines can cause polymerization

Hazardous Decomposition Products: may include carbon dioxide or carbon monoxide amines and hydrocarbons.

Hazardous Polymerization: \_\_\_X\_\_\_ MAY OCCUR \_\_\_ WILL NOT OCCUR

Conditions to Avoid: Contamination with strong acids, bases, or mercaptans.

#### VI. CONTROL AND PROTECTIVE MEASURES

Respiratory Protection (Specify Type):

Protective Gloves: **Chemical resistant gloves**

Eye Protection: **Chemical resistant goggles**

Ventilation to be Used:

\_\_\_ Local Exhaust

\_\_\_X\_\_\_ Mechanical (general)

\_\_\_ Special

\_\_\_ Other

Other Protective Clothing and Equipment: **Wash after using.** Segregate all cleaning apparatus.

Hygienic Work Practices: Avoid contamination of skin.

#### VII. PRECAUTIONS FOR SAFE HANDLING AND USE / LEAK PROCEDURES

Steps to be Taken if Material is Spilled or Released: Wash with water. Dike all spills; absorb with inert material and collect for disposal.

Waste Disposal Methods: Incinerate or use biological treatment in accordance with Federal, State and Local Regulations.

Precautions to be Taken in Handling and Storage      Store at room temperature.

**NON-REGULATED**